

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst.Engineer)
(Re-G.O.MS.20/70/PWD Dt. 23.01.1970)

1	Name of the officer	NIDEESH V.S
2	Name of the School	ASOKA WORLD SCHOOL
3	Location with name of Education District/Sub.District	ERNAKULAM, ELAMAKKARA
4	Classification of Building as specified in column 4 of the application for fitness and size.	G+2, Height 13.91m
5	Period for which the certificates is issued	2022 - 2023
6	Nature of defects, if any	Nil
	a) Foundation and basement	
	b) Superstructure	
	c) Doors and Windows	
	d) Wood work wrought and put up	
	e) Roof	
	f) Flooring	
	g) Miscellaneous (Cracks, etc)	
7	Any major defects noticed which will render the building unsafe in any manner	
8	Whether maintenance works have been done properly	Yes

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the school building was inspected by me on 5/8/22 And found to be fit/~~unfit~~ to conduct classes, for the period 2022 - 2023 For the reasons stated above. Under Normal Weather Conditions

Place: Edappally
Date: 14/02/23



Nideesh. V.S.
Assistant Engineer
Corporation of Cochin
Zonal Office, Edappally